

CAPS

INTERNATIONAL

STEPS TO SCREEN RECLAMATION

- | <u>STEP</u> | <u>PROCEDURE</u> |
|--------------------|---|
| 1. | Degrease screen (D-Haze if necessary). |
| 2. | Dry screen thoroughly. |
| 3. | Apply emulsion evenly. |
| 4. | Dry screen thoroughly. |
| 5. | Expose screen. |
| 6. | Wash image out of screen with water. |
| 7. | Dry screen thoroughly. |
| 8. | Block out pin holes and open spaces with block out. |
| 9. | Dry screen thoroughly. |
| 10. | Print job. |
| 11. | Clean ink off screen with ink remover. |
| 12. | Clean screen with emulsion remover. |
| 13. | Return to step 1. |